

| 编号 | 品牌  | 型号     | 款式      | 遥控器 IC 物编     | 机器 MCU 物编     | 遥控器组件物编         | 备注 |
|----|-----|--------|---------|---------------|---------------|-----------------|----|
| 1  | TCL | 2502   | RC-C09T | 13-0SC301-0SB | 13-M06VAT-00P | 08-002502-RMY   |    |
| 2  | TCL | 2911   | RC-E16T | 13-M34280-M1P | 13-M19V2P-Z34 | 08-002911-RMY   |    |
| 3  | TCL | 1418T  | RC-C16T | 13-LC7461-M0B | 13-A01V01-A0P | 06-RMT008-XX0   |    |
| 4  | TCL | 1420E  | RC-C12T | 13-LC7461-M0B | 13-86F344-8AP | 08-01420E-RMY   |    |
| 5  | TCL | 1425E  | RC-C12T | 13-LC7461-M0B | 13-A01V01-A0P | 08-01425E-RMY   |    |
| 6  | TCL | 1436A  | RC-B01  | 13-6134G6-48B | 13-TCLM5C-03P | 08-01436A-RMY   |    |
| 7  | TCL | 1437A  | RC-B01  | 13-6134G6-48B | 13-TCLM5C-03P | 08-01437A-RMY   |    |
| 8  | TCL | 1475S  | RC-F28T | 13-00AS12-13B | 13-A04V02-TOP | 08-01475S-RMY   |    |
| 9  | TCL | 2101AS | RC-038  | 13-9028F0-22P | 13-TCLM5C-010 | 08-0178A-RMY    |    |
| 10 | TCL | 2101C  | RC-B01  | 13-9028F0-22P | 13-TCLM5C-03P | 08-02101C-HSY   |    |
| 11 | TCL | 2103C  | RC-B01  | 13-9028F0-22P | 13-TCLM5C-03P | 08-2101FR-HSY   |    |
| 12 | TCL | 2103CF | RC-B01  | 13-9028F0-22P | 13-TCLM5C-03P | 08-2103CF-RMY   |    |
| 13 | TCL | 2109E  | RC-C07T | 13-LC7461-M0B | 13-TCLM16-V2P | 08-2109E0-RMY   |    |
| 14 | TCL | 2110G  |         | 13-KS5185-0DE | 13-TCLM5C-03P | 08-02110G-RMY   |    |
| 15 | TCL | 2110GW |         | 13-LC7461-M0B | 13-TCLM16-V2P | 08-2110GW-RMY   |    |
| 16 | TCL | 2111DI | RC-E09T | 13-M34280-M1B | 13-M19V1P-Z34 | 08-2111DI-RMY   |    |
| 17 | TCL | 2113EI | RC-C07T | 13-TDA980-1AP | 13-TCLM16-V3P | 08-2113EI-RMY   |    |
| 18 | TCL | 2113T  | RC-C14T | 13-LC7461-M0B | 13-A01V01-A0P | 08-02113T-RMY   |    |
| 19 | TCL | 2113TW | RC-C14T | 13-LC7461-M0B | 13-A01V01-A0P | 08-2113TW-RMY   |    |
| 20 | TCL | 2115D  | RC-E03T | 13-M34280-M1P | 13-00Z902-34P | 08-02115D-RMY   |    |
| 21 | TCL | 2116D  | RC-E03T | 13-M34280-M1B | 13-M19V2P-Z34 | 08-02116D-RMY   |    |
| 22 | TCL | 2116DI | RC-E09T | 13-TDA980-1AP | 13-M19V2P-Z34 | 08-2116DI-RMY   |    |
| 23 | TCL | 2116E  | RC-C01T | 13-LC7461-M0B | 13-TCLM16-V2P | 08-02116E-RMY   |    |
| 24 | TCL | 2116EF | RC-C01T | 13-LC7461-M0B | 13-TCLM16-V2P | 08-2116EF-RMY   |    |
| 25 | TCL | 2116EG | RC-C01T | 13-LC7461-M0B | 13-TCLM16-V2P | 06-011W32-A101X |    |
| 26 | TCL | 2118E  | RC-C07T | 13-LC7461-M0B | 13-TCLM16-V2P | 08-02118E-RMY   |    |
| 27 | TCL | 2118EF | RC-C01T | 13-LC7461-M0B | 13-TCLM16-V2P | 08-2118EF-RMY   |    |
| 28 | TCL | 2118EW | RC-C01T | 13-LC7461-M0B | 13-TCLM16-V2P | 08-2118EW-RMY   |    |
| 29 | TCL | 2133E  | RC-C07T | 13-LC7461-M0B | 13-TCLM16-V2P | 08-02133E-RMY   |    |
| 30 | TCL | 2135A  | RC-B07T | 13-6134G6-48B | 13-TCLM05-V4P | 08-02135A-RMY   |    |
| 31 | TCL | 2136A  | RC-B06T | 13-6134G6-48B | 13-TCLM5C-03P | 08-02136A-RMY   |    |
| 32 | TCL | 2136C  | RC-B06T | 13-6134G6-48B | 13-TCLM5C-03P | 08-02101C-HSY   |    |
| 33 | TCL | 2136G  | RC-E33T | 13-M34280-M1P | 13-00Z902-34P | 08-02136G-RMY   |    |
| 35 | TCL | 2139A  | RC-B02T | 13-KS5185-0DE | 13-TCLM5C-03P | 08-02166B-RMY   |    |
| 36 | TCL | 2139D  |         | 13-M34280-M1B | 13-00Z902-34P | 08-02139D-RMY   |    |
| 37 | TCL | 2139W  |         | 13-9028F0-22B | 13-274020-00P | 08-02139W-RMY   |    |

|    |     |         |         |               |               |               |  |
|----|-----|---------|---------|---------------|---------------|---------------|--|
| 38 | TCL | 2156A   | RC-B06T | 13-9028F0-22P | 13-TCLM5C-030 | 08-02156A-RMN |  |
| 39 | TCL | 2169A   | R-B06T  | 13-9028F0-22P | 13-TCLM5C-03P | 08-02101C-HSY |  |
| 40 | TCL | 2175DI  | RC-E19T | 13-M34280-M1P | 13-M19V2P-Z34 | 08-2175DI-RMY |  |
| 41 | TCL | 2175E   | RC-C01T | 13-LC7461-M0B | 13-TCLM16-V2P | 08-02175E-RMY |  |
| 42 | TCL | 2175EB  | RC-C01T | 13-LC7461-M0B | 13-TCLM16-V2P | 08-2175EB-RMY |  |
| 43 | TCL | 2175EI  | RC-C01T | 13-LC7461-M0B | 13-TCLM16-V3P | 08-2175EI-RMY |  |
| 44 | TCL | 2178A   | RC-B06T | 13-6134G6-48B | 13-TCLM5C-03P | 08-02178A-RMY |  |
| 45 | TCL | 2180BE  |         | 13-LC7461-M0B | 13-TCLM16-V2P | 08-2180EB-RMY |  |
| 46 | TCL | 2180G   | RC-E13T | 13-M34280-M1B | 13-M19V2P-Z34 | 08-02180G-RMY |  |
| 47 | TCL | 2188BD  |         | 13-M34280-M1B | 13-M19V2P-Z34 | 08-2188BD-RMY |  |
| 48 | TCL | 2188DI  | RC-E50T | 13-M34280-M1B | 13-M19V2P-Z34 | 08-2188DI-RMY |  |
| 49 | TCL | 2188EB  |         | 13-LC7461-M0B | 13-TCLM16-V2P | 08-2188EB-RMY |  |
| 50 | TCL | 2188G   |         | 13-M34280-M1B | 13-M19V2P-Z34 | 08-02180G-RMY |  |
| 51 | TCL | 21A106  | RC-B07T | 13-6134G6-48B | 13-TCLM05-V4P | 08-21A106-RMY |  |
| 52 | TCL | 2588DB  |         | 13-M34280-M1B | 13-M19V2P-Z34 | 08-2588DB-RMY |  |
| 53 | TCL | 2588DB  | RC-E16T | 13-M34280-M1B | 13-M19V2P-Z34 | 08-2588DB-RMY |  |
| 54 | TCL | 25A106  | RC-F30T | 13-0SC301-0SB | 13-TCLM06-VBP | 08-TCA106-RMY |  |
| 55 | TCL | 25A106F |         | 13-0SC301-0SB | 13-TCLM06-VBP | 08-TCF106-RMY |  |
| 56 | TCL | 2901A   |         | 13-0SC301-0SB | 13-TCLM06-V6P | 08-02901A-HSY |  |
| 57 | TCL | 2129C   |         | 13-9028F0-22P | 13-274020-00P | 08-02129C-HSY |  |
| 58 | TCL | 2511F   |         | 13-M34280-M1B | 13-M37221-M6R | 08-02511F-RMY |  |
| 59 | TCL | 2515DZ  |         | 13-M34280-M1B | 13-M11V3P-M6S | 08-2515DZ-RMY |  |
| 60 | TCL | 2515DZ  | RC-E07T | 13-M34280-M1B | 13-M11V3P-M6S | 08-2515DZ-RMY |  |
| 61 | TCL | 2516B   |         | 13-M34280-M1P | 13-M11V3P-M6S | 08-02516B-RMY |  |
| 62 | TCL | 2516BI  | RC-E11T | 13-M34280-M1P | 13-M18V3P-M8B | 08-2516BI-RMY |  |
| 63 | TCL | 2516BP  |         | 13-M34280-M1B | 13-M11V3P-M6S | 08-2516BP-RMY |  |
| 64 | TCL | 2516BZ  |         | 13-M34280-M1B | 13-M11V3P-M6S | 08-2516BZ-RMY |  |
| 65 | TCL | 2516EF  |         | 13-LC7461-M0B | 13-A04V01-A0P | 08-2516EF-RMY |  |
| 66 | TCL | 2518E   | RC-C08T | 13-LC7461-M0B | 13-A04V01-A0P | 08-02518E-RMY |  |
| 67 | TCL | 2518EF  |         | 13-LC7461-M0B | 13-A04V01-A0P | 08-2518EF-RMY |  |
| 68 | TCL | 2518EW  | RC-C08T | 13-LC7461-M0B | 13-A04V01-A0P | 08-2518EW-RMY |  |
| 69 | TCL | 2535A   | RC-C11T | 13-SAA301-0TP | 13-TCLM06-VBP | 08-02535A-RMY |  |
| 70 | TCL | 2536F   |         | 13-0SC301-0SB | 13-TCLM06-V6P | 08-02536F-HSY |  |
| 71 | TCL | 2536G   |         | 13-M34280-M1B | 13-M19V2P-Z34 | 08-02510G-RMY |  |
| 72 | TCL | 2536W   |         | 13-0SC301-0SB | 13-M06VAT-00P | 08-02536W-RMY |  |
| 73 | TCL | 2539D   | RC-E06T | 13-M34280-M1B | 13-M37221-M6R | 08-02539D-RMY |  |
| 74 | TCL | 2566B   |         | 13-0SC301-0SB | 13-OCTV22-2SP | 08-002566-HSY |  |
| 75 | TCL | 2575D   |         | 13-M34280-M1P | 13-M19V2P-Z34 | 08-02575D-RMY |  |

|     |     |         |         |               |               |               |  |
|-----|-----|---------|---------|---------------|---------------|---------------|--|
| 76  | TCL | 2580DB  |         | 13-M34280-M1P | 13-M19V2P-Z34 | 08-2580DB-RMY |  |
| 77  | TCL | 2906A   | RC-C11T | 13-SAA301-0TP | 13-TCLM06-VBP | 08-02906A-RMY |  |
| 78  | TCL | 2906E   |         | 13-LC7461-M0B | 13-A04V01-A0P | 08-02906E-RMY |  |
| 79  | TCL | 2906E   | RC-C10T | 13-LC7461-M0B | 13-A04V01-A0P | 08-02906E-RMY |  |
| 80  | TCL | 2909A   |         | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02909A-HSY |  |
| 81  | TCL | 2909B   |         | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02909B-RMY |  |
| 82  | TCL | 2909B   | RC-C09T | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02909B-RMY |  |
| 83  | TCL | 2910G   | RC-E16T | 13-M34280-M1B | 13-M19V2P-Z34 | 08-02910G-RMY |  |
| 84  | TCL | 2910GW  |         | 13-OSC301-0SB | 13-TCLM06-V7P | 08-2910GW-RMY |  |
| 85  | TCL | 2911    |         | 13-M34280-M1B | 13-M19V2P-Z34 | 08-002911-RMY |  |
| 86  | TCL | 2911DI  | RC-E10T | 13-M34280-M1B | 13-M18V3P-M8B | 08-2911DI-RMY |  |
| 87  | TCL | 2911DZ  | RC-E04T | 13-M34280-M1B | 13-M37221-M6R | 08-2911DZ-RMY |  |
| 88  | TCL | 2913A   |         | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02913A-RMY |  |
| 89  | TCL | 2913E   | RC-C08T | 13-LC7461-M0B | 13-A04V01-A0P | 08-02913E-RMY |  |
| 90  | TCL | 2913EB  | RC-C08T | 13-LC7461-M0B | 13-A04V01-A0P | 08-2913EP-RMY |  |
| 91  | TCL | 2913UI  | RC-F46T | 13-SAA301-0TB | 13-TDA938-3NP | 08-2913UI-RMY |  |
| 92  | TCL | 2915DZ  | RC-E27T | 13-M34280-M1B | 13-M11V3P-M6S | 08-2915DZ-RMY |  |
| 93  | TCL | 2916D   | RC-F06T | 13-M34280-M1B | 13-M11V3P-M6S | 08-02916D-RMY |  |
| 94  | TCL | 2916P   |         | 13-SC9028-23B | 13-TCLM03-V1P | 08-02916P-RMY |  |
| 95  | TCL | 2916P   | RC-D01T | 13-SC9028-23B | 13-TCLM03-V1P | 08-02916P-RMY |  |
| 96  | TCL | 2918E   | RC-C10T | 13-LC7461-M0B | 13-TCLM28-V1P | 08-02918E-RMY |  |
| 97  | TCL | 2918EW  | RC-C10T | 13-LC7461-M0B | 13-A04V01-A0P | 08-2918EW-RMY |  |
| 98  | TCL | 2919AZ  | RC-041  | 13-OSC301-0SB | 13-TCLM06-V6P | 08-2919AZ-RMY |  |
| 99  | TCL | 2926UI  | RC-F46T | 13-SAA301-0TB | 13-TDA938-3NP | 08-2926UI-RMY |  |
| 100 | TCL | 2927D   | RC-E59T | 13-M34280-M1P | 13-M19V2P-Z34 | 08-02927D-RMY |  |
| 101 | TCL | 2927D   | RC-E35T | 13-M34280-M1P | 13-M19V2P-Z34 | 08-02927D-RMY |  |
| 102 | TCL | 2939D   |         | 13-M34280-M1B | 13-M37221-M6R | 08-02939D-RMY |  |
| 103 | TCL | 2939DR  |         | 13-M34280-M1P | 13-M37221-M6R | 08-2939DR-RMY |  |
| 104 | TCL | 2939R   |         | 13-M34280-M1B | 13-M37221-M6R | 08-02939R-RMY |  |
| 105 | TCL | 2939W   |         | 13-OSC301-0SB | 13-TCLM06-V7P | 08-02939W-RMY |  |
| 106 | TCL | 2952AL  |         | 13-OSC301-0SB | 13-274020-00P | 08-2952AL-RMY |  |
| 107 | TCL | 2952B   |         | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02952B-RMY |  |
| 108 | TCL | 2956D   |         | 13-M34280-M1B | 13-M19V2P-Z34 | 08-02956D-RMY |  |
| 109 | TCL | 2956D   | RC-F64T | 13-M34280-M1B | 13-M19V2P-Z34 | 08-02956D-RMY |  |
| 110 | TCL | 2966A/G | RC-042  | 13-SAA301-0TP | 13-TCLM06-V3P | 08-02966A-RMY |  |
| 111 | TCL | 2966DG  |         | 13-M34280-M1B | 13-M37221-M6R | 08-2966DG-RMY |  |
| 112 | TCL | 2966F   |         | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02966A-RMY |  |
| 113 | TCL | 2966G   |         | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02966A-RMY |  |

|     |     |          |          |               |               |               |  |
|-----|-----|----------|----------|---------------|---------------|---------------|--|
| 114 | TCL | 2966G-2  |          | 13-OSC301-0SB | 13-8C3216-40P | 08-2966G2-RMY |  |
| 115 | TCL | 2966GL   | RC-C04T  | 13-OSC301-0SB | 13-TCLM06-V7P | 08-2966GL-RMY |  |
| 116 | TCL | 2966GL   |          | 13-OSC301-0SB | 13-TCLM06-V7P | 08-2966GL-RMY |  |
| 117 | TCL | 2966GL   | RC-C04T  | 13-OSC301-0SB | 13-TCLM06-V7P | 08-2966GL-RMY |  |
| 118 | TCL | 2966N    | RC-076N1 | 13-SAA301-0TP | 13-8C3216-40P | 08-02966N-HSY |  |
| 119 | TCL | 2966T    |          | 13-SC9028-23B | 13-8C3216-40P | 08-02966T-RMY |  |
| 120 | TCL | 2966X    |          | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02966X-RMY |  |
| 121 | TCL | 2968AZ   |          | 13-OSC301-0SB | 13-TCLM06-V6P | 08-2968AZ-RMY |  |
| 122 | TCL | 2968SZ   | RC-075   | 13-SAA301-0TP | 13-8C3216-37P | 08-288200-002 |  |
| 123 | TCL | 2969A    | RC-035   | 13-SAA301-0TP | 13-OCTV22-2SP | 08-277320-001 |  |
| 124 | TCL | 2969C    |          | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02969C-RMY |  |
| 125 | TCL | 2975D    |          | 13-M34280-M1B | 13-M11V3P-M6S | 08-02975D-RMY |  |
| 126 | TCL | 2977E    |          | 13-LC7461-M0B | 13-A04V01-A0P | 08-02977E-RMY |  |
| 127 | TCL | 2977E    | RC-C10T  | 13-LC7461-M0B | 13-A04V01-A0P | 08-02977E-RMY |  |
| 128 | TCL | 2980DB   | RC-E16T  | 13-M34280-M1B | 13-M19V2P-Z34 | 08-2980DB-RMY |  |
| 129 | TCL | 2980G    | RC-F02T  | 13-M34280-M1B | 13-M37221-M6R | 08-02980G-RMY |  |
| 130 | TCL | 2980GI   |          | 13-M34280-M1B | 13-M18V2P-M8B | 08-2980GI-RMY |  |
| 131 | TCL | 2980P    |          | 13-SC9028-23B | 13-TCLM03-V1P | 08-02980P-RMY |  |
| 132 | TCL | 2980P    | RC-D01T  | 13-SC9028-23B | 13-TCLM03-V1P | 08-02980P-RMY |  |
| 133 | TCL | 2988BD   |          | 13-M34280-M1B | 13-M11V3P-M6S | 08-2988BD-RMY |  |
| 134 | TCL | 2988BD   | RC-F02T  | 13-M34280-M1B | 13-M11V3P-M6S | 08-2988BD-RMY |  |
| 135 | TCL | 2988DB   | RC-E16T  | 13-M34280-M1B | 13-M19V2P-Z34 | 08-2988DB-RMY |  |
| 136 | TCL | 2988DB   | RC-E35T  | 13-M34280-M1B | 13-M19V2P-Z34 | 08-2988DB-RMY |  |
| 137 | TCL | 2988DF   |          | 13-M34280-M1B | 13-M11V3P-M6S | 08-2988DF-RMY |  |
| 138 | TCL | 2988DI   | RC-F13T  | 13-M34280-M1P | 13-M18V3P-M8B | 08-2988DI-RMY |  |
| 139 | TCL | 2988G    |          | 13-M34280-M1B | 13-M37221-M6R | 08-2988GT-RMY |  |
| 140 | TCL | 2999UZ   | RC-F18T  | 13-OSC301-0SB | 13-TDA938-3NP | 08-2999UZ-RMY |  |
| 141 | TCL | 2999UZ   | RC-F39T  | 13-OSC301-0SB | 13-TDA938-3NP | 08-2999UZ-RMY |  |
| 142 | TCL | 29U186Z  |          | 13-OSC301-0SB | 13-TDA938-3NP | 08-BU186Z-RMY |  |
| 143 | TCL | 29U186ZG | RC-F41T  | 13-SAA301-0TP | 13-TDA938-3NP | 08-BU186G-RMY |  |
| 144 | TCL | 3416DF   |          | 13-M34280-M1B | 13-M18V3P-M8B | 08-3416DF-RMY |  |
| 145 | TCL | 3416DI   | RC-F09T  | 13-M34280-M1B | 13-M18V2P-M8B | 08-3416DI-RMY |  |
| 146 | TCL | 3416P    |          | 13-OSC301-0SB | 13-8C3216-40P | 08-03416P-RMY |  |
| 147 | TCL | 3416PB   |          | 13-OSC301-0SB | 13-S88P83-24P | 08-3416PB-RMY |  |
| 148 | TCL | 3418D    | RC-F11T  | 13-M34280-M1B | 13-M11V4P-M6S | 08-03418D-RMY |  |
| 149 | TCL | 3418E    | RC-C08T  | 13-LC7461-M0B | 13-TCLM28-V1P | 08-03418E-RMY |  |
| 150 | TCL | 3433D    | RC-F11T  | 13-M34280-M1B | 13-M11V3P-M6S | 08-03433D-RMY |  |
| 151 | TCL | 3433DZ   | RC-F11T  | 13-M34280-M1B | 13-M11V4P-M6S | 08-3433DZ-RMY |  |

|     |     |              |         |               |               |                 |  |
|-----|-----|--------------|---------|---------------|---------------|-----------------|--|
| 152 | TCL | 3438D        |         | 13-M34280-M1B | 13-M37221-EAP | 08-03438D-RMY   |  |
| 153 | TCL | 3438DR       |         | 13-M34280-M1B | 13-M37221-M6R | 08-3438DR-RMY   |  |
| 154 | TCL | 3438FPR      | RC-07FP | 13-SC9028-23B | 13-TCLM03-V1P | 08-272880-003   |  |
| 155 | TCL | 3438PB       | RC-074  | 13-OSC301-OSB | 13-S88P83-24P | 08-3438PB-RMY   |  |
| 156 | TCL | 3438R        |         | 13-OSC301-OSB | 13-8C3216-40P | 08-273900-001   |  |
| 157 | TCL | 3460D        | RC-F10T | 13-M34280-M1B | 13-M11V4P-M6S | 08-03460D-RMY   |  |
| 158 | TCL | 3480GI       | RC-F09T | 13-M34280-M1B | 13-M18V2P-M8B | 08-3480GI-RMY   |  |
| 159 | TCL | 3488BD       | RC-F09T | 13-M34280-M1B | 13-M18V3P-M8B | 08-3488BD-RMY   |  |
| 160 | TCL | 3488D        | RC-F06T | 13-M34280-M1B | 13-M18V3P-M8B | 08-3488BD-RMY   |  |
| 161 | TCL | 3488GI       |         | 13-M34280-M1B | 13-M18V2P-M8B | 08-3488GI-RMY   |  |
| 162 | TCL | 34D106       | RC-F10T | 13-M34280-M1B | 13-M11V3P-M6S | 08-AD1060-RMY   |  |
| 163 | TCL | 3811DI       | RC-F01T | 13-M34280-M1B | 13-M18V3P-M8B | 08-3811DI-RMY   |  |
| 164 | TCL | AT2570UB     | RC-F55T | 13-C73C03-02B | 13-A01V01-PHP | 08-2570UB-RMY   |  |
| 165 | TCL | AT2575       |         | 13-M34280-M1B | 13-M11V3P-M6S | 08-AT2575-RMY   |  |
| 166 | TCL | AT2575D      | RC-E18T | 13-M34280-M1P | 13-M19V2P-Z34 | 08-T2575D-RMY   |  |
| 167 | TCL | AT2575F      |         | 13-M34280-M1B | 13-M11V3P-M6S | 08-T2575F-RMY   |  |
| 168 | TCL | AT2575I      | RC-E23T | 13-M34280-M1B | 13-M18V3P-M8B | 08-T2575I-RMY   |  |
| 169 | TCL | AT2575S      | RC-N    | 13-00AS12-13B | 13-A01V10-TOP | 06-0N0030-B1102 |  |
| 170 | TCL | AT2588D      | RC-E18T | 13-M34280-M1B | 13-M19V2P-Z34 | 08-T2588D-RMY   |  |
| 171 | TCL | AT2590       |         | 13-M34280-M1B | 13-M11V3P-M6S | 08-AT2586-RMY   |  |
| 172 | TCL | AT2590I      | RC-E26T | 13-M34280-M1P | 13-M18V3P-M8B | 08-T2590I-RMY   |  |
| 173 | TCL | AT2590UB     | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D014X |  |
| 174 | TCL | AT2590UB     | RC-F48T | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D014X |  |
| 175 | TCL | AT2590UB     | RC-F63T | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D014X |  |
| 176 | TCL | AT25E159     |         | 13-LC7461-M0B | 13-86F354-8AP | 08-TCE159-RMY   |  |
| 177 | TCL | AT25S135     | RC-F30T | 13-0UPD61-34B | 13-A8809C-PNP | 08-TCS135-RMY   |  |
| 178 | TCL | AT25S168     |         | 13-0UPD61-34B | 13-A8809C-PNP | 08-TCS168-RMY   |  |
| 179 | TCL | AT25U159     |         | 13-OSC301-OSB | 13-TDA938-3NP | 08-TCU159-RMY   |  |
| 180 | TCL | AT29106/S    |         | 13-00AS12-13B | 13-A01V01-TOP | 08-TBS106-RMY   |  |
| 181 | TCL | AT29106B     | RC-R10T | 13-ASC121-2CB | 13-A01V01-PHP | 08-TBU106-RMY   |  |
| 182 | TCL | AT2911P      |         | 13-SC9028-23B | 13-P88PS3-8NP | 08-T2911P-RMY   |  |
| 183 | TCL | AT29128      | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D007X |  |
| 184 | TCL | AT2915       | RC-E37T | 13-M34280-M1P | 13-M11V3P-M6S | 08-AT2915-RMY   |  |
| 185 | TCL | AT2915DZ     |         | 13-M34280-M1P | 13-M11V3P-M6S | 08-T2915Z-RMY   |  |
| 186 | TCL | AT29166G     | RC-R02T | 13-OSC301-OSB | 13-A01V01-PHP | 08-TBU166-RMY   |  |
| 187 | TCL | AT29166GF/UL |         | 13-C73C03-02B | 13-A01V01-PHP | 08-TB166F-RMY   |  |
| 188 | TCL | AT29166UL    |         | 13-00AS12-13B | 13-A01V01-PHP | 08-T29166-RMY   |  |
| 189 | TCL | AT2916U      | RC-F42T | 13-PCA852-1BB | 13-TDA938-OMS | 08-T2916U-RMY   |  |

|     |     |                   |          |               |               |                 |  |
|-----|-----|-------------------|----------|---------------|---------------|-----------------|--|
| 190 | TCL | AT2916U           | RC-F22T  | 13-PCA852-1BB | 13-TDA938-OMS | 08-T2916U-RMY   |  |
| 191 | TCL | AT2916UG          | RC-F22T  | 13-C73C03-02B | 13-TDA938-3NP | 08-T2916G-RMY   |  |
| 192 | TCL | AT2916UG/UL (F)   | RC-R     | 13-C73C03-02B | 13-TDA938-3NP | 08-T2916G-RMY   |  |
| 193 | TCL | 2918E, 2513E      |          | 13-LC7461-M0B | 13-TCLM28-V1P | 08-02918E-RMY   |  |
| 194 | TCL | 2938SZ, 2868SZ    | RC-099SZ | 13-SAA301-0TP | 13-OCTV22-2SP | 08-272050-004   |  |
| 195 | TCL | 2916D, 3488D      | RC-F06T  | 13-M34280-M1B | 13-M11V3P-M6S | 08-02916D-RMY   |  |
| 196 | TCL | 2910DZ, 2911DZ    |          | 13-M34280-M1B | 13-M18V3P-M8B | 08-2911DI-RMY   |  |
| 197 | TCL | 2911D, 2910       | RC-E05T  | 13-M34280-M1B | 13-M37221-M6R | 08-02911D-RMY   |  |
| 198 | TCL | 1425E, 1418T      |          | 13-LC7461-M0B | 13-A01V01-A0P | 06-RMT008-XX0   |  |
| 199 | TCL | 2106A, 21A106     | RC-B07T  | 13-6134G6-48B | 13-TCLM05-V4P | 08-02106A-RMY   |  |
| 200 | TCL | 2113E, 2188EB     | RC-C07T  | 13-LC7461-M0B | 13-TCLM16-V2P | 08-02113E-MAN   |  |
| 201 | TCL | 2169, 2509S, 2908 | RC-035   | 13-SAA301-0TP | 13-OCTV22-2SP | 08-297280-001   |  |
| 202 | TCL | 2118E, 2518E      |          | 13-LC7461-M0B | 13-TCLM16-V2P | 08-02118E-RMY   |  |
| 203 | TCL | 2136D, 2139D      | RC-E03T  | 13-M34280-M1P | 13-00Z902-34P | 08-02139D-RMY   |  |
| 204 | TCL | 2516D, 2511D      | RC-E06T  | 13-M34280-M1P | 13-M37221-M6R | 08-02511D-RMY   |  |
| 205 | TCL | AI2960            |          | 13-6134G6-48B | 13-A03V01-TOP | 08-AI2960-RMY   |  |
| 206 | TCL | AT21106           |          | 13-ASC121-2CB | 13-A04V01-TOP | 08-TDS106-RMY   |  |
| 207 | TCL | AT21106/S         |          | 13-00AS12-13B | 13-A04V02-TOP | 08-TDS106-RMY   |  |
| 208 | TCL | AT2116/Y          | RC-C     | 13-TK7461-TDB | 13-WS9301-A0P | 06-0C0244-B001X |  |
| 209 | TCL | AT21166G          |          | 13-0SC301-0SB | 13-A02V02-PHP | 08-TD166G-RMY   |  |
| 210 | TCL | AT21166G/U        |          | 13-0SC301-0SB | 13-A02V02-PHP | 08-TD166G-RMY   |  |
| 211 | TCL | AT21266/Y         | RC-R     | 13-TK7461-SPB | 13-A02V02-PHP | 06-0R0235-I001X |  |
| 212 | TCL | AT2126E           | RC-C19T  | 13-LC7461-M0B | 13-A01V01-SYP | 08-T2126E-RMY   |  |
| 213 | TCL | AT2127/S          |          | 13-00AS12-13B | 13-A04V01-TOP | 08-T2127S-RMY   |  |
| 214 | TCL | AT29286           |          | 13-C73C03-02B | 13-A01V01-PHP | 08-T29286-RMY   |  |
| 215 | TCL | AT29286/UL        |          | 13-C73C03-02B | 13-A01V01-PHP | 08-T29286-RMY   |  |
| 216 | TCL | AT29286/UL (I)    | RC-R     | 13-C73C03-02B | 13-A01V01-PHP | 08-T29286-RMY   |  |
| 217 | TCL | AT29329/UL        | RC-R     | 13-00AS12-13B | 13-0TDA93-73P | 06-0R1735-H009X |  |
| 218 | TCL | AT2935I           | RC-E41T  | 13-M34280-M1B | 13-4X21QW-R4B | 08-T2935I-RMY   |  |
| 219 | TCL | AT2956            | RC-E20T  | 13-M34280-M1B | 13-M11V3P-M6S | 08-AT2956-RMY   |  |
| 220 | TCL | AT2956B           | RC-E43T  | 13-M34280-M1B | 13-M11V3P-M6S | 08-T2956B-RMY   |  |
| 221 | TCL | AT2960/S          |          | 13-0UPD61-34B | 13-A01V01-TOP | 08-T2960S-RMY   |  |
| 222 | TCL | AT2960B           | RC-R05T  | 13-C73C03-02B | 13-A01V01-PHP | 08-T2960B-RMY   |  |
| 223 | TCL | AT2965            | RC-F61T  | 13-PCA852-1BB | 13-TDA938-OMS | 08-T2965U-RMY   |  |
| 224 | TCL | AT2965U           | RC-F38T  | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0036-A1151 |  |
| 225 | TCL | AT2970I           | RC-E41T  | 13-M34280-M1P | 13-4X21QW-R4B | 08-T2927I-RMY   |  |
| 226 | TCL | AT2970U           |          | 13-0SC301-0SB | 13-TDA938-3NP | 08-T2970U-RMY   |  |
| 227 | TCL | AT2975            | RC-F62T  | 13-C73C03-02B | 13-A01V01-PHP | 08-T2975U-RMY   |  |



|     |     |                        |         |               |               |                 |  |
|-----|-----|------------------------|---------|---------------|---------------|-----------------|--|
| 228 | TCL | AT2975D                | RC-E47T | 13-M34280-M1B | 13-M11V3P-M6S | 08-T2975D-RMY   |  |
| 229 | TCL | AT2975I                | RC-E24T | 13-M34280-M1B | 13-M18V3P-M8B | 08-T2975I-RMY   |  |
| 230 | TCL | AT2975Z                | RC-E21T | 13-M34280-M1B | 13-M11V3P-M6S | 08-T2975Z-RMY   |  |
| 231 | TCL | AT2980DB               |         | 13-M34280-M1B | 13-M11V3P-M6S | 08-T2980B-RMY   |  |
| 232 | TCL | AT2986Z                | RC-F15T | 13-M34280-M1B | 13-M11V3P-M6S | 08-T2986Z-RMY   |  |
| 233 | TCL | AT2988D                | RC-E18T | 13-M34280-M1P | 13-M19V2P-Z34 | 08-T2988D-RMY   |  |
| 234 | TCL | AT2988D(P)             |         | 13-M34280-M1P | 13-M19V2P-Z34 | 08-T2988D-RMY   |  |
| 235 | TCL | AT2988DB               |         | 13-M34280-M1B | 13-M11V3P-M6S | 08-T2988B-RMY   |  |
| 236 | TCL | AT2988U                | RC-F63T | 13-C73C03-02B | 13-A01V01-PHP | 08-T2988U-RMY   |  |
| 237 | TCL | AT2990B                |         | 13-R01V1R-MSK | 13-M11V4P-M6S | 08-T2990B-RMY   |  |
| 238 | TCL | AT2990I                |         | 13-R01V1R-MSK | 13-M18V3P-M8B | 08-T2990I-RMY   |  |
| 239 | TCL | AT2990U                | RC-F48T | 13-00AS12-13B | 13-A01V01-PHP | 08-T2990U-RMY   |  |
| 240 | TCL | AT29S168               |         | 13-0UPD61-34B | 13-A01V01-TOP | 08-TBS168-RMY   |  |
| 241 | TCL | AT29S168B              |         | 13-00AS12-13B | 13-A01V10-TOP | 08-TB168B-RMY   |  |
| 242 | TCL | AT29U159               | RC-F43T | 13-0SC301-0SB | 13-TDA938-3NP | 08-TBU159-RMY   |  |
| 243 | TCL | AT29U186               |         | 13-0SC301-0SB | 13-TDA938-3NP | 08-TBU186-RMY   |  |
| 244 | TCL | AT3416U                | RC-F26T | 13-PCA852-1BB | 13-TDA938-0MS | 08-T3416U-RMY   |  |
| 245 | TCL | AT3416U                | RC-F40T | 13-PCA852-1BB | 13-TDA938-0MS | 08-T3416U-RMY   |  |
| 246 | TCL | AT34189B               | RC-R    | 13-18L901-SCB | 13-H13V02-TOP | 06-0N0930-C008X |  |
| 247 | TCL | AT34276                | RC-R02T | 13-M34280-M1B | 13-M18V3P-M8B | 08-T3480I-RMY   |  |
| 248 | TCL | AT34276/UL             | RC-R    | 13-M34280-M1B | 13-M18V3P-M8B | 08-T3480I-RMY   |  |
| 249 | TCL | AT34276/UL, AT34286/UL | RC-R    | 13-M34280-M1B | 13-M18V3P-M8B | 08-T3480I-RMY   |  |
| 250 | TCL | AT3460D                | RC-E49T | 13-M34280-M1B | 13-A01V01-MIP | 08-T3460D-RMY   |  |
| 251 | TCL | AT3480GI               | RC-F14T | 13-M34280-M1B | 13-M18V3P-M8B | 08-T3480I-RMY   |  |
| 252 | TCL | AT3486DI               | RC-F14T | 13-M34280-M1B | 13-M18V3P-M8B | 08-T3486I-RMY   |  |
| 253 | TCL | AT3486DZ               | RC-F15T | 13-M34280-M1B | 13-M11V4P-M6S | 08-T3486Z-RMY   |  |
| 254 | TCL | AT3486I                | RC-E41T | 13-M34280-M1B | 13-4X21QW-R4B | 08-T3486I-RM1   |  |
| 255 | TCL | AT3488DZ               | RCF14T  | 13-M34280-M1B | 13-M18V3P-M8B | 08-T3488Z-RMY   |  |
| 256 | TCL | AT3488S                |         | 13-00AS12-13B | 13-A01V01-TOP | 06-0N0030-B1102 |  |
| 257 | TCL | AT34U186/UL            | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0034-B1132 |  |
| 258 | TCL | B2180I                 |         | 13-M34280-M1B | 13-M19V2P-Z34 | 08-B2180I-RMY   |  |
| 259 | TCL | B2580                  |         | 13-M34280-M1B | 13-M11V3P-M6S | 08-0B2580-RMY   |  |
| 260 | TCL | B2980                  |         | 13-M34280-M1B | 13-M37221-M6R | 08-02980G-RMY   |  |
| 261 | TCL | C2133                  | RC-B03T | 13-LC7461-M0B | 13-M16V1P-00P | 08-002133-RMY   |  |
| 262 | TCL | C2133E                 |         | 13-LC7461-M0B | 13-TCLM16-V2P | 08-C2133E-RMY   |  |
| 263 | TCL | C2533                  |         | 13-0SC301-0SB | 13-TCLM06-V6P | 08-0C2533-RMY   |  |
| 264 | TCL | DTV2912                | RC-E08T | 13-SC9028-23B | 13-274020-00P | 08-DT2912-HSY   |  |

|     |     |                     |         |               |               |                 |  |
|-----|-----|---------------------|---------|---------------|---------------|-----------------|--|
| 265 | TCL | DTV2912B            | RC-E25T | 13-SC9028-23B | 13-274020-00P | 08-D2912B-HSY   |  |
| 266 | TCL | DTV2912U            |         | 13-SC9028-23B | 13-274020-00P | 08-D2912U-RMY   |  |
| 267 | TCL | HID25192P           | RC-G01T | 13-SC9028-23B | 13-P88PS3-8NP | 08-HC192P-RMY   |  |
| 268 | TCL | HiD31A01H/GU21      | RC-Q    | 13-18L901-SCB | 13-P88PS3-4NP | 06-0Q1932-A005X |  |
| 269 | TCL | HiD3290H/GU21       | RC-Q    | 13-18L901-SCB | 13-P88PS3-4NP | 06-0Q1931-A004X |  |
| 270 | TCL | HiD329SW. P         | RC-G01T | 13-SC9028-23B | 13-274020-00P | 08-H329WP-RMY   |  |
| 271 | TCL | HiD34181P           |         | 13-SC9028-23B | 13-4X21QW-R4B | W8-H34181-RMY   |  |
| 272 | TCL | HiD34181P/R         |         | 13-SC9028-23B | 13-4X21QW-R4B | W8-H34181-RMY   |  |
| 273 | TCL | HiD360SW. P         | RC-G01T | 13-SC9028-23B | 13-274020-00P | 08-H360WP-RMY   |  |
| 274 | TCL | HiD361SW            | RC-G    | 13-SC9028-23B | 13-274020-00P | 06-0G3336-A006X |  |
| 275 | TCL | HiD38215P           | RC-G    | 13-SC9028-23B | 13-274020-00P | 06-0G0334-AA231 |  |
| 276 | TCL | HiD432              | RC-R    | 13-18L901-SCB | 13-A8827P-0NP | 06-0R1936-A001X |  |
| 277 | TCL | HiD4328G            |         | 13-SC9028-23B | 13-274020-00P | 08-H4328G-RMY   |  |
| 278 | TCL | HID4328S            | RC-G    | 13-SC9028-23B | 13-274020-00P | 06-0G3336-B005X |  |
| 279 | TCL | HiD435B. r          |         | 13-SC9028-23B | 13-274020-00P | 08-H435BR-RMY   |  |
| 280 | TCL | HiD438BR            |         | 13-SC9028-23B | 13-274020-00P | 08-H438BR-RMY   |  |
| 281 | TCL | HiD438SB. r         |         | 13-SC9028-23B | 13-274020-00P | 06-0G3336-B005X |  |
| 282 | TCL | HID5226             |         | 13-SC9028-23B | 13-274020-00P | 08-HD5226-RMY   |  |
| 283 | TCL | HiD5226             |         | 13-SC9028-23B | 13-274020-00P | 08-HD5226-RMY   |  |
| 284 | TCL | HiD5228G            |         | 13-SC9028-23B | 13-274020-00P | 08-H5228G-RMY   |  |
| 285 | TCL | HiD5228S            | RC-G    | 13-SC9028-23B | 13-274020-00P | 06-0G3336-B11D1 |  |
| 286 | TCL | HiD522B. R          |         | 13-SC9028-23B | 13-274020-00P | 06-0G3336-B008X |  |
| 287 | TCL | HiD525              | RC-G    | 13-SC9028-23B | 13-274020-00P | 06-0G3336-B001X |  |
| 288 | TCL | HiD525BR            |         | 13-SC9028-23B | 13-274020-00P | 08-H525BR-RMY   |  |
| 289 | TCL | HiD526BR            |         | 13-SC9028-23B | 13-274020-00P | 08-H526BR-RMY   |  |
| 290 | 乐华  | 29B1P/MV22          | RC-R    | 13-00AS12-13B | 13-P93CS4-5FB | 06-0R1035-D025X |  |
| 291 | 乐华  | 29V1P/N22           | RC-Q    | 13-18L901-SCB | 13-CF2V01-NTP | 06-0Q0936-B001X |  |
| 292 | 乐华  | 34V1P/N22           | RC-N    | 13-18L901-SCB | 13-CF2V01-NTP | 06-0N0929-C001X |  |
| 293 | TCL | HiD2960P            |         | 13-SC9028-23B | 13-P88PS3-8NP | 08-H2960P-RMY   |  |
| 294 | TCL | HiD296S. p          |         | 13-SC9028-23B | 13-274020-00P | 08-H296SP-RMY   |  |
| 295 | TCL | HiD2988I            | RC-E41T | 13-M34280-M1B | 13-4X21QW-R4B | 08-H2988I-RMY   |  |
| 296 | TCL | HiD299. N           |         | 13-SC9028-23B | 13-274020-00P | 08-DT2990-HSY   |  |
| 297 | TCL | HiD299. P           |         | 13-SC9028-23B | 13-274020-00P | 08-D2990B-RMY   |  |
| 298 | TCL | HiD2990P            | RC-G01T | 13-SC9028-23B | 13-P88PS3-8NP | 08-H2990P-RMY   |  |
| 299 | TCL | HiD2990p, HiD29166p | RC-G01T | 13-SC9028-23B | 13-P88PS3-8NP | 08-H2990P-RMY   |  |
| 300 | TCL | HID2992I            | RC-F47T | 13-SC9028-23B | 13-7281EK-SPP | 08-H2992I-RMY   |  |
| 301 | TCL | HiD299S. p          |         | 13-SC9028-23B | 13-274020-00P | 08-H299SP-RMY   |  |
| 302 | TCL | HiD291P             | RC-G01T | 13-TC9028-23B | 13-274020-00P | 08-HI291P-RMY   |  |



|     |     |                     |         |               |               |                 |  |
|-----|-----|---------------------|---------|---------------|---------------|-----------------|--|
| 303 | TCL | HiD291SP            | RC-G01T | 13-9028F0-23P | 13-274020-00P | 08-H291SP-RMY   |  |
| 304 | TCL | HiD29206P           | RC-N    | 13-18L901-SCB | 13-0CF3V1-NTP | 06-0N0930-C008X |  |
| 305 | TCL | AT29189B/UL         | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0035-B1121 |  |
| 306 | TCL | AT29192             |         | 13-C73C03-02B | 13-TDA938-3NP | 08-TBU192-RMY   |  |
| 307 | TCL | AT29192U            |         | 13-C73C03-02B | 13-TDA938-3NP | 08-TBU192-RMY   |  |
| 308 | TCL | AT29215Z            | RC-R05T | 13-C73C03-02B | 13-A01V01-PHP | 08-TA2152-RMY   |  |
| 309 | TCL | AT29215Z/U          |         | 13-C73C03-02B | 13-A01V01-PHP | 08-TA2152-RMY   |  |
| 310 | TCL | AT2565/UL (F)       | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0032-B1151 |  |
| 311 | TCL | AT2565/UL (I)       | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0032-B1151 |  |
| 312 | TCL | AT2565A/US21        | RC-R    | 13-18L901-SCB | 13-TDA937-6PP | 06-0R1935-J024X |  |
| 313 | TCL | AT2570B, AT2570U    | RC-F21T | 13-0SC301-0SB | 13-TDA938-3NP | 08-T2570B-RMY   |  |
| 314 | TCL | HiD34286P           |         | 13-M34280-M1B | 13-4X21QW-R4B | 08-T2970I-RM1   |  |
| 315 | TCL | HiD3460I            | RC-E41T | 13-M34280-M1B | 13-4X21QW-R4B | 08-H3460I-RMY   |  |
| 316 | TCL | HiD34728P/N         | RC-G    | 13-SC9028-23B | 13-P88PS3-8NP | 06-0G3334-A005X |  |
| 317 | TCL | HiD34728S/R         | RC-L    | 13-SC9028-23B | 13-P88PS3-8NP | 06-0L0342-A001X |  |
| 318 | TCL | HiD348. e           |         | 13-9028F0-23P | 13-274020-00P | 08-HI348P-RMY   |  |
| 319 | TCL | HiD348P             | RC-G01T | 13-9028F0-23P | 13-274020-00P | 08-HI348P-RMY   |  |
| 320 | TCL | HiD348S. P          |         | 13-TC9028-23B | 13-274020-00P | 08-H348SP-RMY   |  |
| 321 | TCL | HiD348SP            | RC-G01T | 13-TC9028-23B | 13-274020-00P | 08-H348SP-RMY   |  |
| 322 | TCL | HiD2960P            |         | 13-SC9028-23B | 13-P88PS3-8NP | 08-H2960P-RMY   |  |
| 323 | TCL | HiD296S. p          |         | 13-SC9028-23B | 13-274020-00P | 08-H296SP-RMY   |  |
| 324 | TCL | HiD2988I            | RC-E41T | 13-M34280-M1B | 13-4X21QW-R4B | 08-H2988I-RMY   |  |
| 325 | TCL | HiD299. N           |         | 13-SC9028-23B | 13-274020-00P | 08-DT2990-HSY   |  |
| 326 | TCL | HiD299. P           |         | 13-SC9028-23B | 13-274020-00P | 08-D2990B-RMY   |  |
| 327 | TCL | HiD2990P            | RC-G01T | 13-SC9028-23B | 13-P88PS3-8NP | 08-H2990P-RMY   |  |
| 328 | TCL | HiD2990p, HiD29166p | RC-G01T | 13-SC9028-23B | 13-P88PS3-8NP | 08-H2990P-RMY   |  |
| 329 | TCL | HID2992I            | RC-F47T | 13-SC9028-23B | 13-7281EK-SPP | 08-H2992I-RMY   |  |
| 330 | TCL | HiD299S. p          |         | 13-SC9028-23B | 13-274020-00P | 08-H299SP-RMY   |  |
| 331 | TCL | HiD291P             | RC-G01T | 13-TC9028-23B | 13-274020-00P | 08-HI291P-RMY   |  |
| 332 | TCL | HiD291SP            | RC-G01T | 13-9028F0-23P | 13-274020-00P | 08-H291SP-RMY   |  |
| 333 | TCL | HiD29206P           | RC-N    | 13-18L901-SCB | 13-0CF3V1-NTP | 06-0N0930-C008X |  |
| 334 | TCL | AT29189B/UL         | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0035-B1121 |  |
| 335 | TCL | AT29192             |         | 13-C73C03-02B | 13-TDA938-3NP | 08-TBU192-RMY   |  |
| 336 | TCL | AT29192U            |         | 13-C73C03-02B | 13-TDA938-3NP | 08-TBU192-RMY   |  |
| 337 | TCL | AT29215Z            | RC-R05T | 13-C73C03-02B | 13-A01V01-PHP | 08-TA2152-RMY   |  |
| 338 | TCL | AT29215Z/U          |         | 13-C73C03-02B | 13-A01V01-PHP | 08-TA2152-RMY   |  |
| 339 | TCL | AT2565/UL (F)       | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0032-B1151 |  |
| 340 | TCL | AT2565/UL (I)       | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0032-B1151 |  |

|     |     |                         |          |               |               |                 |  |
|-----|-----|-------------------------|----------|---------------|---------------|-----------------|--|
| 341 | TCL | AT2565A/US21            | RC-R     | 13-18L901-SCB | 13-TDA937-6PP | 06-0R1935-J024X |  |
| 342 | TCL | 3406D, 34D106           | RC-E49T  | 13-M34280-M1P | 13-M37225-ECP | 08-03406D-RMY   |  |
| 343 | TCL | 3409                    |          | 13-0SC301-0SB | 13-8C3216-40P | 08-282510-002   |  |
| 344 | TCL | 3409D                   | RC-F11T  | 13-M34280-M1B | 13-M11V3P-M6S | 08-03409D-RMY   |  |
| 345 | TCL | 3409NI                  | RC-076NI | 13-SAA301-0TP | 13-TA8759-BNP | 08-3409NI-HSY   |  |
| 346 | TCL | AI2560, AI2960          |          | 13-6134G6-48B | 13-A03V01-TOP | 08-AI2560-RMY   |  |
| 347 | TCL | AT21179G, AT21S135      |          | 13-00AS12-13B | 13-A04V02-TOP | 08-T2179G-RMY   |  |
| 348 | TCL | AT21181/UL              | RC-R     | 13-00AS12-13B | 13-A02V02-PHP | 06-0R1035-D018X |  |
| 349 | TCL | AT21181/UL12            | RC-R     | 13-00AS12-13B | 13-A02V02-PHP | 06-0R1035-D018X |  |
| 350 | TCL | AT21189/E               | RC-R09T  | 13-00AS12-13B | 13-A01V01-SYP | 08-TD189E-RMY   |  |
| 351 | TCL | AT21189B/UL, AT21276/UL | RC-R     | 13-C73C03-02B | 13-A02V02-PHP | 06-0R0032-B1161 |  |
| 352 | TCL | AT21211A                | RC-R     | 13-00AS12-13B | 13-A02V02-PHP | 06-0R1035-D002X |  |
| 353 | TCL | AT21215/U               |          | 13-C73C03-02B | 13-A02V02-PHP | 08-T2170U-RMY   |  |
| 354 | TCL | AT21215U                |          | 13-C73C03-02B | 13-A02V02-PHP | 08-T2170U-RMY   |  |
| 355 | TCL | AT21228/AT21289         | RC-R     | 13-00AS12-13B | 13-A04V02-TOP | 06-0N0028-B1111 |  |
| 356 | TCL | AT21276/UL12            | RC-R     | 13-C73C03-02B | 13-A02V01-PHP | 06-0R0032-B1161 |  |
| 357 | TCL | AT21281/S               | RC-N     | 13-00AS12-13B | 13-A04V02-TOP | 06-0N0028-B100X |  |
| 358 | TCL | AT21286/UL, AT2170/U    | RC-R     | 13-00AS12-13B | 13-A02V02-PHP | 06-0R1035-D013X |  |
| 359 | TCL | AT21286/UL, AT2170U     | RC-R     | 13-00AS12-13B | 13-A02V02-PHP | 06-0R1035-D006X |  |
| 360 | TCL | AT21286/UL12            | RC-R     | 13-00AS12-13B | 13-A02V02-PHP | 06-0R1035-D021X |  |
| 361 | TCL | AT21289/E               | RC-R     | 13-00AS12-13B | 13-A01V01-SYP | 06-0R1035-F016X |  |
| 362 | TCL | AT2135E, AT21E106       | RC-C     | 13-LC7461-M0B | 13-A01V01-SYP | 06-0C0231-A3331 |  |
| 363 | TCL | AT2156, AT2186, FM2156  | RC-E18T  | 13-M34280-M1B | 13-M19V2P-Z34 | 08-AT2156-RMY   |  |
| 364 | TCL | AT2170                  | RC-F56T  | 13-C73C03-02B | 13-A02V01-PHP | 08-T2170U-RMY   |  |
| 365 | TCL | AT2170B                 | RC-E18T  | 13-M34280-M1B | 13-M19V2P-Z34 | 08-T2170B-RMY   |  |
| 366 | TCL | AT2170D                 | RC-E18T  | 13-M34280-M1B | 13-M19V2P-Z34 | 08-T2170D-RMY   |  |
| 367 | TCL | AT2170DI, AT2170D       |          | 13-M34280-M1B | 13-M19V2P-Z34 | 08-T2170I-RMY   |  |
| 368 | TCL | AT2175/S                | RC-N     | 13-00AS12-13B | 13-A04V02-TOP | 06-0N0030-B005X |  |
| 369 | TCL | AT2175/UL, AT2113/UL    | RC-R     | 13-C73C03-02B | 13-A02V02-PHP | 06-0R0032-B1161 |  |
| 370 | TCL | AT2175EB                |          | 13-LC7461-M0B | 13-A01V01-SYP | 08-T2175B-RMY   |  |
| 371 | TCL | AT2188EB                | RC-C19T  | 13-LC7461-M0B | 13-A01V01-SYP | 08-T2188B-RMY   |  |
| 372 | TCL | AT2190                  |          | 13-LC7461-M0B | 13-M25V1P-00P | 08-AT2190-RMY   |  |
| 373 | TCL | AT2190B                 |          | 13-R01V1R-MSK | 13-M25V1P-00P | 08-T2190B-RMY   |  |
| 374 | TCL | AT2190I                 | RC-E17T  | 13-M34280-M1B | 13-M19V2P-Z34 | 08-T2190I-RMY   |  |
| 375 | TCL | AT2570B, AT2570U        | RC-F21T  | 13-0SC301-0SB | 13-TDA938-3NP | 08-T2570B-RMY   |  |
| 376 | TCL | C2533E, C2533-F         |          | 13-LC7461-M0B | 13-TCLM16-V2P | 08-C2133E-RMY   |  |

|     |     |                        |         |               |                 |                 |  |
|-----|-----|------------------------|---------|---------------|-----------------|-----------------|--|
| 377 | TCL | AT25135/UL             |         | 13-00AS12-13B | 13-A01V01-PHP   | 08-TC106B-RMY   |  |
| 378 | TCL | AT2515                 |         | 13-M34280-M1B | 13-M11V3P-M6S   | 08-AT2515-RMY   |  |
| 379 | TCL | AT2515DZ               | RC-E20T | 13-M34280-M1B | 13-M11V3P-M6S   | 08-T2515Z-RMY   |  |
| 380 | TCL | AT21D159               | RC-E18T | 13-M34280-M1B | 13-A08V02-ZLP   | 08-TDD159-RMY   |  |
| 381 | TCL | AT21S135               | RC-F28T | 13-0UPD61-34B | 13-A8803C-PNP   | 08-21S135-RMY   |  |
| 382 | TCL | AT21S179, AT21S192     | RC-F34T | 13-0UPD61-34B | 13-A8803C-PNP   | 08-TDS179-RMY   |  |
| 383 | TCL | AT21S192               | RC-F34T | 13-00AS12-13B | 13-A04V02-TOP   | 08-TDS192-RMY   |  |
| 384 | TCL | AT25106/S              |         | 13-0UPD61-34B | 13-A01V01-TOP   | 08-TCS106-RMY   |  |
| 385 | TCL | AT25166G, AT29166G     | RC-R02T | 13-0SC301-0SB | 13-A01V01-PHP   | 08-TCU166-RMY   |  |
| 386 | TCL | HiD34189PB             |         | 13-18L901-SCB | 13-A8809C-PNP   | 06-0N0930-C002X |  |
| 387 | TCL | HiD34276P/N            |         | 13-SC9028-23B | 13-P88PS3-8NP   | 08-H3476P-RMY   |  |
| 388 | TCL | AT25166G/U             |         | 13-0SC301-0SB | 13-A01V01-PHP   | 08-TCU166-RMY   |  |
| 389 | TCL | AT25166G/U             |         | 13-0SC301-0SB | 13-A01V01-PHP   | 08-TCU166-RMY   |  |
| 390 | TCL | AT25166U/AT25166G      |         | 13-0SC301-0SB | 13-A01V01-PHP   | 08-TCU166-RMY   |  |
| 391 | TCL | AT2516Y, AT2916Y       | RC-F    | 13-TK7461-TDB | 13-WS9321-A0P   | 06-0F0246-B001X |  |
| 392 | TCL | AT25181/UL, AT25276/UL | RC-R    | 13-00AS12-13B | 13-A01V01-PHP   | 06-0R1035-D001X |  |
| 393 | TCL | AT25189/E, AT25289/E   | RC-R    | 13-00AS12-13B | 13-A02V01-SYP   | 06-0R0032-A1171 |  |
| 394 | TCL | AT2570UI, AT2570B      | RC-F44T | 13-0SC301-0SB | 13-TDA938-3NP   | 08-T2570B-RMY   |  |
| 395 | TCL | AT2586, AT2590, AT2590 | RC-E20T | 13-M34280-M1B | 13-M11V3P-M6S   | 08-AT2586-RMY   |  |
| 396 | TCL | AT2586, AT2590         | RC-E20T | 13-M34280-M1B | 13-M11V3P-M6S   | 08-AT2586-RMY   |  |
| 397 | TCL | AT2590UB, AT25S135     | RC-F63T | 13-00AS12-13B | 13-A01V01-PHP   | 06-0R1035-D014X |  |
| 398 | TCL | AT2590UB, AT2990U      | RC-F48T | 13-00AS12-13B | 13-A01V01-PHP   | 06-0R1035-D014X |  |
| 399 | TCL | 3438D/L, 3438PR        | RC-072  | 13-M34280-M1B | 13-M37221-EAP   | 08-03438D-RMY   |  |
| 400 | TCL | 3416DI, 3480GI         | RC-F09T | 13-M34280-M1B | 13-M18V2P-M8B   | 08-3416DI-RMY   |  |
| 401 | TCL | HiD55P8H, HiD42P1H     | RC-G    | 13-SC9028-23B | 13-274020-00P   | 06-0G3336-B010X |  |
| 402 | TCL | J2118, J2518           | RC-X    | 13-AS1216-A0B | 13-P88PS3-8NP   | 06-0X0705-A001X |  |
| 403 | TCL | J2118A, J1418A         | RC-X    | 13-00AS12-13B | 13-86F354-8AP   | 06-0X0005-B003X |  |
| 404 | TCL | LCD2726                |         | 11-0BC337-0BX | 13-V212MV-64B   | 08-LD1526-RMY   |  |
| 405 | TCL | LCD3026                | RC-N    | 13-00AS12-13B | 13-V212MV-64B   | 06-0N0030-D004X |  |
| 406 | TCL | NT21A11/UL12           | RC-R    | 13-00AS12-13B | 13-A02V02-PHP   | 06-0R1035-D002X |  |
| 407 | TCL | NT21A31                | RC-R    | 13-00AS12-13B | 13-TOUL12-01M00 | 06-0R1035-D021X |  |
| 408 | TCL | NT21A41B/UL12          |         | 13-00AS12-13B | 13-TOUL12-01M00 | 06-016W31-A000X |  |
| 409 | TCL | NT21A51/UL12           | RC-R    | 13-00AS12-13B | 13-TOUL12-01M00 | 06-0R1035-D021X |  |
| 410 | TCL | RPT-4302M              |         | 13-M34280-M1P | 13-SDA958-9XB   | 08-RT4302-RMY   |  |

|     |     |                                                |         |               |               |                 |  |
|-----|-----|------------------------------------------------|---------|---------------|---------------|-----------------|--|
| 411 | TCL | HiD29181P/R                                    |         | 13-SC9028-23B | 13-4X21QW-R4B | W8-H29181-RMY   |  |
| 412 | TCL | HiD29189PB                                     | RC-N    | 13-18L901-SCB | 13-A8809C-PNP | 06-0N0930-C002X |  |
| 413 | TCL | HiD29166P/N                                    |         | 13-SC9028-23B | 13-P88PS3-8NP | 08-HB166P-RMY   |  |
| 414 | TCL | HiD29168P/R                                    |         | 13-SC9028-23B | 13-4X21QW-R4B | W8-H29168-RMY   |  |
| 415 | TCL | AT2556                                         | RC-E20T | 13-M34280-M1B | 13-M11V3P-M6S | 08-AT2556-RMY   |  |
| 416 | TCL | AT2560B                                        | RC-R05T | 13-C73C03-02B | 13-A01V01-PHP | 08-T2560B-RMY   |  |
| 417 | TCL | AT25215Z                                       | RC-R05T | 13-00AS12-13B | 13-A01V01-PHP | 08-TC215Z-RMY   |  |
| 418 | TCL | AT25215Z/U                                     |         | 13-00AS12-13B | 13-A01V01-PHP | 08-TC215Z-RMY   |  |
| 419 | TCL | 2102, 2136A, 2156A, 2169A                      | RC-B06T | 13-9028F0-22P | 13-TCLM5C-03P | 08-002102-RM1   |  |
| 420 | TCL | 2528/SZ/Z, 2868, 2938Z                         | RC-093  | 13-SAA301-0TP | 13-OCTV22-2SP | 08-272050-001   |  |
| 421 | TCL | 2906E, 2918E/EW, 2977E                         | RC-C10T | 13-LC7461-M0B | 13-A04V01-A0P | 08-02906E-RMY   |  |
| 422 | TCL | 29A1, 29B2, N25B2                              | RC-N    | 13-00AS12-13B | 13-A8827P-0NP | 06-0R1035-H022X |  |
| 423 | TCL | AT34106S, AT2575S                              | RC-N    | 13-00AS12-13B | 13-A01V01-TOP | 06-0N0030-B1102 |  |
| 424 | TCL | AT2986Z, AT3486DZ                              | RC-F15T | 13-M34280-M1B | 13-M11V3P-M6S | 08-T2986Z-RMY   |  |
| 425 | TCL | AT2965/U, AT29229/UL                           | RC-R    | 13-PCA852-1BB | 13-TDA938-OMS | 08-T2965U-RMY   |  |
| 426 | TCL | AT2965U, AT34U186                              | RC-F25T | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0036-A1151 |  |
| 427 | TCL | AT2965U, AT34U186                              | RC-F38T | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0036-A1151 |  |
| 428 | TCL | AT25276, AT25181                               | RC-R    | 13-C73C03-02B | 13-A01V01-PHP | 06-0R1035-D001X |  |
| 429 | TCL | AT25276/UL                                     | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D001X |  |
| 430 | TCL | AT25276G/UL                                    |         | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D001X |  |
| 431 | TCL | 2501F                                          |         | 13-SAA301-0TP | 13-TCLM06-V6P | 08-02501A-HSY   |  |
| 432 | TCL | 2128SZ, 2129SZ                                 | RC-036  | 13-SAA301-0TP | 13-OCTV22-2SP | 08-296290-001   |  |
| 433 | TCL | 2133, C2133                                    | RC-B03T | 13-LC7461-M0B | 13-M16V1P-00P | 08-002133-RMY   |  |
| 434 | TCL | 2501A, 2901A, 2909A                            | RC-040  | 13-SAA301-0TP | 13-274020-00P | 08-02501A-HSY   |  |
| 435 | TCL | 2502, 2907, 2909B,                             | RC-C09T | 13-SAA301-0TP | 13-M06VAT-00P | 08-002502-RMY   |  |
| 436 | TCL | 2502D                                          | RC-E30T | 13-M34280-M1B | 13-M19V2P-Z34 | 08-02502D-RMY   |  |
| 437 | TCL | AT25286/UL                                     | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D003X |  |
| 438 | TCL | AT25286/UL                                     | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D003X |  |
| 439 | TCL | AT2927U                                        | RC-F22T | 13-PCA852-1BB | 13-TDA938-OMS | 08-T2927U-RMY   |  |
| 440 | 乐华  | 29B1, S29B2                                    | RC-R    | 13-00AS12-13B | 13-A8827P-0NP | 06-0R1035-H021X |  |
| 441 | TCL | AT34276/UL (F), AT25286/UL (F), AT29286/UL (F) | RC-R    | 13-M34280-M1B | 13-M18V3P-M8B | 08-T3480I-RMY   |  |
| 442 | TCL | 2501C, 2503C, 2511C, 2536C, 2568C              |         | 13-SAA301-0TP | 13-M06VAT-00P | 08-02501C-HSY   |  |
| 443 | TCL | 2501C, 2510C, 2511C, 2                         | RC-039  | 13-SAA301-0TP | 13-M06VAT-00P | 08-02501C-HSY   |  |

|     |     |                                                                                |                                 |               |               |                 |  |
|-----|-----|--------------------------------------------------------------------------------|---------------------------------|---------------|---------------|-----------------|--|
|     |     | 536C, 2901C, 2909C, C2533                                                      |                                 |               |               |                 |  |
| 444 | TCL | 2988D, 3409D, 3418D, 3433D                                                     | FC-F11T                         | 13-M34280-M1B | 13-M37221-M6R | 08-02988D-RM1   |  |
| 445 | TCL | 1419, 9614C, 9621B/C/D, 9625B/BZ, 2968/Z, 2969, 9629B/BZ                       | RC-032, RC-061R, RC-064, RC-091 | 13-9012F0-11P | 13-P47C83-4AP | 08-02166B-RM3   |  |
| 446 | TCL | 1475S/S12, 1419/S12                                                            | RC-R                            | 13-00AS12-13B | 13-A01V14-TOP | 06-OR1035-K001X |  |
| 447 | TCL | 1701, 2128/S, 2129/S, 2566, 2566B, 2568, 2969A                                 | RC-033, RC-092                  | 13-SAA301-0TP | 13-OCTV22-2SP | 可代 RC-012       |  |
| 448 | TCL | 1701AS, 2101AS, 2129A, 2136A, 2166B, 1436A                                     | RC-038                          | 13-9028F0-22P | 13-TCLM5C-010 | 08-02136A-RMY   |  |
| 449 | TCL | 2111D, 2136D/G, 2139D, 2975D                                                   | RC-E03T                         | 13-LC7461-M0B | 13-TCLM16-V2P | 08-02111D-RMY   |  |
| 450 | TCL | 2116E, 2118E, C2133E, 2175E                                                    | RC-C01T                         | 13-LC7461-M0B | 13-TCLM16-V2P | 08-C2133E-RMY   |  |
| 451 | TCL | AT21228/S12, AT21266B/S, AT21281S                                              | RC-N                            | 13-00AS12-13B | 13-A04V02-TOP | 06-0N0028-B1111 |  |
| 452 | TCL | 2506A, 2535A, 2906A, 295A106                                                   | RC-C11T                         | 13-SAA301-0TP | 13-TCLM06-VBP | 08-02506A-RMY   |  |
| 453 | TCL | 2510G, 2536G, 2575D, 2580DB, 2588DB, 2910G, 2911, 2927D, 2956D, 2980DB, 2988DB | RC-E16T                         | 13-M34280-M1P | 13-M19V2P-Z34 | 08-02510G-RMY   |  |
| 454 | TCL | 2511D, 2511DR, 2516D                                                           |                                 | 13-M34280-M1B | 13-M11V3P-M6S | 08-02511D-RMY   |  |
| 455 | TCL | 2511DI, 2511DZ, 2515DZ, 2539DI                                                 | RC-E07T                         | 13-M34280-M1B | 13-M18V3P-M8B | 08-2511DI-RMY   |  |
| 456 | TCL | 2511DR, 2516B/D, 2539D/DR                                                      | RC-E06T                         | 13-M34280-M1B | 13-M37221-M6R | 08-02511D-RMY   |  |
| 457 | TCL | 2511DZ, 2910DZ, 2911DZ                                                         | RC-E04T                         | 13-M34280-M1P | 13-M11V3P-M6S | 08-2511DZ-RMY   |  |
| 458 | TCL | 2580G, 2588BD, 2916DZ, 2980G, 2988BD, B2980                                    | RC-F02T                         | 13-M34280-M1P | 13-M37221-M6R | 08-02580G-RMY   |  |
| 459 | TCL | 2580GT, 2580G, B2580T                                                          |                                 | 13-M34280-M1B | 13-M18V2P-M8B | 08-2580GI-RMY   |  |
| 460 | TCL | 2901C, 2909C, 2966A/C/G                                                        | RC-039, RC-40, RC-042           | 13-OSC301-0SB | 13-TCLM06-V6P | 08-02901C-HSY   |  |
| 461 | TCL | 2910, 2910D, 2911D, 2916D, 2939D/DR/H                                          | RC-E05T                         | 13-M34280-M1B | 13-M37221-M6R | 08-02911D-RMY   |  |
| 462 | TCL | 2910, 2911F, 2910D, 29                                                         |                                 | 13-M34280-M1B | 13-M37221-M6R | 08-02911D-RMY   |  |

|     |     |                                                                                             |                 |               |               |                 |  |
|-----|-----|---------------------------------------------------------------------------------------------|-----------------|---------------|---------------|-----------------|--|
|     |     | 11D                                                                                         |                 |               |               |                 |  |
| 463 | TCL | 2952, 2966, 2966GA, 2976S, 3409                                                             | RC-078, RC-078B | 13-OSC301-0SB | 13-8C3216-40P | 08-296250-001   |  |
| 464 | TCL | 2952, 2976S                                                                                 |                 | 13-OSC301-0SB | 13-8C3216-40P | 08-296250-001   |  |
| 465 | TCL | HiD25181H/N22, HiD29206H/N22, HiD34189H/N22                                                 | RC-Q            | 13-18L901-SCB | 13-CF2V01-NTP | 06-0Q0936-B001X |  |
| 466 | TCL | AT21228/S, AT21211/S, AT21228/S, AT21207/S                                                  | RC-N            | 13-00AS12-13B | 13-A04V02-TOP | 06-0N0028-B1111 |  |
| 467 | TCL | AT2115, AT2170B/D, AT21D59, AT2575D, AT2588D, AT2988D                                       | RC-E18T         | 13-M34280-M1B | 13-M19V2P-Z34 | 08-AT2115-RMY   |  |
| 468 | TCL | AT21288/S, AT21230/S, AT21211/S, AT21288/S(F), AT21211S(F), AT21228/S, AT21207/S, AT21231/S | RC-N            | 13-00AS12-13B | 13-A04V02-TOP | 06-0N0028-B1111 |  |
| 469 | TCL | AT2165/UL12, AT2165/UL, AT21189B/UL12, AT21266A/UL12, AT21181B/UL12                         |                 | 13-M34280-M1B | 13-M19V2P-Z34 |                 |  |
| 470 | TCL | 3416, 3416D, 3460D, 3486, 3488D, 34D106                                                     | RC-F10T         | 13-M34280-M1B | 13-M11V3P-M6S | 08-003416-RMY   |  |
| 471 | TCL | AT21181/UL(I), AT2165I, AT2165(I)                                                           | RC-R            | 13-00AS12-13B | 13-A02V02-PHP | 06-0R1035-D018X |  |
| 472 | TCL | AT2190U, AT2190U/N, AT21266A/UL, AT21206/UL, AT2190U/F                                      | RC-F51T         | 13-SAA301-0TB | 13-A02V02-PHP | 06-011W33-A101X |  |
| 473 | TCL | AT25106B, AT2960B, AT2975/B                                                                 | RC-F62T         | 13-C73C03-02B | 13-A01V01-PHP | 08-TC106B-RMY   |  |
| 474 | TCL | AT25166/UL, AT25276, AT25181/UL                                                             | RC-R            | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D011X |  |
| 475 | TCL | AT2516U, AT2916U, AT2927U                                                                   | RC-F22T         | 13-PCA852-1BB | 13-TDA938-OMS | 08-T2516U-RMY   |  |
| 476 | TCL | 3488D, AT3480GI, AT3486DI/DZ, AT3488DZ                                                      | RC-F14T         | 13-M34280-M1B | 13-M18V3P-M8B | 08-3488BD-RMY   |  |
| 477 | TCL | AT25206/UL, AT29128/UL, AT29386/UL, AT34281/UL                                              | RC-R            | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D007X |  |
| 478 | TCL | AT25289/E(F), AT25189, AT25289E, AT                                                         | RC-R            | 13-00AS12-13B | 13-A02V01-SYP | 06-0R0032-A1171 |  |



|     |     |                                                       |         |               |               |                 |  |
|-----|-----|-------------------------------------------------------|---------|---------------|---------------|-----------------|--|
|     |     | 25289, AT25189E                                       |         |               |               |                 |  |
| 479 | TCL | AT2565, AT25189B/UL, AT2565UL, AT29187/UL, AT34187/UL | RC-R    | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0032-B1151 |  |
| 480 | TCL | AT2565, AT29187, AT34187                              | RC-R08T | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0032-B1151 |  |
| 481 | TCL | AT2570U, AT25U159, AT2970U, AT29U159                  | RC-F31T | 13-0SC301-0SB | 13-TDA938-3NP | 08-T2570U-RMY   |  |
| 482 | TCL | AT2570U, AT25U159, AT2970U, AT29U159                  | RC-F43T | 13-0SC301-0SB | 13-TDA938-3NP | 08-T2570U-RMY   |  |
| 483 | TCL | AT2570UB                                              | RC-F55T | 13-C73C03-02B | 13-A01V01-PHP | 08-2570UB-RMY   |  |
| 484 | TCL | AT2570UB(I), AT25166/U(I), AT29166U(I), AT34286/UL(I) | RC-R    | 13-C73C03-02B | 13-A01V01-PHP | 08-2570UB-RMY   |  |
| 485 | TCL | AT2916UG/UL, AT2516UG/UL                              | RC-R    | 13-C73C03-02B | 13-TDA938-3NP | 08-T2916G-RMY   |  |
| 486 | TCL | AT29187/UL, AT2565/U, AT34187/UL                      | RC-R    | 13-C73C03-02B | 13-A01V01-PHP | 06-0R0032-B1151 |  |
| 487 | TCL | AT29189, AT34189                                      |         | 13-00AS12-13B | 13-86F354-8AP | 06-0R0032-A100X |  |
| 488 | TCL | AT29189/E, AT34189/E, AT29189E(F)                     | RC-R    | 13-00AS12-13B | 13-86F354-8AP | 06-0R0032-A100X |  |
| 489 | TCL | AT29189/E, AT34189/E                                  | RC-R    | 13-00AS12-13B | 13-86F354-8AP | 06-0R0032-A100X |  |
| 490 | TCL | AT29266/Y                                             | RC-R    | 13-TK7461-SPB | 13-WS9322-A0P | 06-0R0235-I002X |  |
| 491 | TCL | AT2927i, AT2935i, AT2970i                             | RC-E41T | 13-M34280-M1P | 13-4X21QW-R4B | 08-T2927I-RMY   |  |
| 492 | TCL | HiD29158HR/GU21, HiD29158R/GU21                       | RC-Q    | 13-18L901-SCB | 13-P88PS3-4NP | 06-0Q1936-A002X |  |
| 493 | TCL | HiD29181HB/MV22, HiD29280H/MV22, HiD34181HB/MV22      | RC-R    | 13-00AS12-13B | 13-P93CS4-5FB | 06-0R1035-D022X |  |
| 494 | TCL | HiD29189PB/N, HiD34189PB/N                            | RC-N    | 13-18L901-SCB | 13-A8809C-PNP | 06-0N0930-C002X |  |
| 495 | TCL | HiD29208P/PH, HiD29207P/PH, HiD29208P                 | RC-Q    | 13-18L901-SCB | 13-H03V01-MIP | 06-0Q1936-A001X |  |
| 496 | TCL | HiD29276H                                             | RC-N    | 13-18L901-SCB | 13-CF2V01-NTP | 06-0N0930-C010X |  |
| 497 | TCL | HiD29276P/N, HiD34189P/N, HiD29189P/N                 | RC-G    | 13-SC9028-23B | 13-P88PS3-8NP | 06-0G0331-A4451 |  |
| 498 | TCL | HiD29286HB, HiD29286H/P21, HiD34286H, HiD34286H/P21   | RC-Q    | 13-00AS12-13B | 13-P93CS4-5FB | 06-0R1035-D024X |  |
| 499 | TCL | HiD29286P, HiD34286P                                  | RC-E41T | 13-M34280-M1B | 13-4X21QW-R4B | 08-HB286P-RMY   |  |

|     |     |                                                                                                                                       |         |               |               |                 |  |
|-----|-----|---------------------------------------------------------------------------------------------------------------------------------------|---------|---------------|---------------|-----------------|--|
| 500 | TCL | HiD432B. r, HiD522B. r<br>, HiD435                                                                                                    | RC-G    | 13-SC9028-23B | 13-274020-00P | 06-0G3336-B008X |  |
| 501 | TCL | J2588, J2988, J2518A,<br>J1988                                                                                                        | RC-X    | 13-AS1216-A0B | 13-Z90231-00P | 06-0X0705-A002X |  |
| 502 | TCL | NT21A21/UL12, NT21A1<br>1/UL11                                                                                                        | RC-R    | 13-00AS12-13B | 13-A02V02-PHP | 06-0R1035-D002X |  |
| 503 | TCL | NT2965B/A21, NT29181<br>/A21, NT34181/A21                                                                                             | RC-J    | 13-AS1218-03B | 13-SDA555-XFP | 06-0J0736-A001X |  |
| 504 | TCL | N14K6/S11, N21B2/S11<br>, N21K3/S11                                                                                                   | RC-N    | 13-00AS12-13B | 13-A04V02-TOP | 06-0N0030-B007X |  |
| 505 | 乐华  | 29A1P/N21, 34A1P/N21<br>, 29V1P                                                                                                       | RC-N    | 13-18L901-SCB | 13-A8809C-PNP | 06-0N0930-C006X |  |
| 506 | 乐华  | 29B1/S21, 29B2/S21, 2<br>9A1/S21, N25B2/S21                                                                                           | RC-N    | 13-00AS12-13B | 13-A01V10-TOP | 06-0N0030-B010X |  |
| 507 | TCL | HiD299. p, HiD2991. p,<br>HiD299s. p, HiD348. p,<br>HiD348S. p                                                                        | RC-G01T | 13-SC9028-23B | 13-274020-00P | 08-D2990B-RMY   |  |
| 508 | TCL | HID29A21/N22, HID342<br>76H/N22, HiD29189H/N<br>22, HID29189H, HiD292<br>76H/N22                                                      | RC-N    | 13-18L901-SCB | 13-CF2V01-NTP | 06-0N0930-C010X |  |
| 509 | TCL | HiD34189P/N, HiD2927<br>6P/N                                                                                                          | RC-G    | 13-SC9028-23B | 13-P88PS3-8NP | 06-0G0331-A4451 |  |
| 510 | 乐华  | N21B1/S12, N21B1L/S1<br>2, N21B2/S12, 21A1/S1<br>2, N21K1/S12, 21V1/S1<br>2, N21K2/S12, N21K3/S<br>12, N14K6/S12                      | RC-R    | 13-00AS12-13B | 13-A01V14-TOP | 06-0R1935-G020X |  |
| 511 | 乐华  | N21K3, N21B2                                                                                                                          | RC-N    | 13-00AS12-13B | 13-A01V14-TOP | 06-0R1935-G020X |  |
| 512 | 乐华  | 25B2/S22, 29B1/S22, 2<br>9B2/S22, N25B2/S22, S<br>29B2/S22                                                                            | RC-R    | 13-00AS12-13B | 13-A01V02-TOP | 06-0N0030-B010X |  |
| 513 | 乐华  | 29A1/S22, 25A1/S22, 2<br>5V1/S22, 29V1/S22, 34<br>A1/S22, 34V1/S22, N25<br>K1/S22, N25K2/S22, N2<br>5K3/S22, S29K1/S22, S<br>34A1/S22 | RC-R    | 13-00AS12-13B | 13-A8827P-0NP | 06-0R1035-H022X |  |
| 514 | TCL | AT25281/S, AT29281/S<br>, AT29266B/S, AT29228<br>/S, AT29211/S, AT2522<br>8/S, AT34266B/S, AT25<br>211/S, AT25288/S, AT2              | RC-N    | 13-00AS12-13B | 13-A01V10-TOP | 06-0N0029-B11D1 |  |

|     |     |                                                                                                                                                                                                                                                                           |      |               |               |                 |  |
|-----|-----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------------|---------------|-----------------|--|
|     |     | 5266B/S                                                                                                                                                                                                                                                                   |      |               |               |                 |  |
| 515 | TCL | HiD34276PB, HiD29206P/N, HiD29276PB, HiD34189PB, HiD34276PB/S, N21, HiD34276H, HiD29228/N21                                                                                                                                                                               | RC-N | 13-00AS12-13B | 13-P93CS4-5FB | 06-0R1035-D024X |  |
| 516 | TCL | AT29228/S, AT29281/S, AT29211/S, AT25230/S, AT25207, AT25281/S, AT25192/S, AT25228/S, AT25266B/S, AT29168/S, AT29266B/S, AT25211/S                                                                                                                                        | RC-N | 13-00AS12-13B | 13-A01V10-TOP | 06-0N0029-B11D1 |  |
| 517 | TCL | AT29281, AT21231/S12, AT25211, AT25288, NT25A71/S22, AT21281/S12, AT21288/S12, AT29228/S22, NT21281C, NT21A61, NT25281C, NT25A61, NT29A51/S22, AT25211/S22, AT25266B/S22                                                                                                  | RC-R | 13-18L901-SCB | 13-A01V02-TOP | 06-0R1935-G019X |  |
| 518 | TCL | HiD29286HB/MV22, HiD34281H/MV22, HiD29A51H/MV22, HiD29A21, HiD34A51H/MV22, HiD29A41H/MV22, HiD34276PB/MV22, HiD25A61H/MV22, HiD29128H/MV22, HiD34286HB/MV22, HiD29211H/MV22, HiD29A21H/MV22                                                                               | RC-R | 13-00AS12-13B | 13-P93CS4-5FB | 06-0R1035-D024X |  |
| 519 | TCL | HiD34A71H/GU21, HiD29181HB/NU22, HiD29A71H/GU21, HiD29A81/NU21, HiD34181H/NU21, HiD29158SP/N, HiD29181H, HiD34158SP/N, HiD34181H, HiD34158H, HiD29A81, HiD34A61H/GU21, HiD34A81/NU21, HiD29189PB/NU22, HiD29A61/GU21, HiD29A81H/GU21, HiD29158H/GU21, HiD34A81H/GU21, HiD | RC-Q | 13-18L901-SCB | 13-P88PS3-4NP | 06-0Q1936-A002X |  |

|     |     |                                                                                                                                                                                                                                                            |      |               |               |                 |  |
|-----|-----|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------------|---------------|-----------------|--|
|     |     | 34158HR/GU21                                                                                                                                                                                                                                               |      |               |               |                 |  |
| 520 | TCL | AT25189B/US21, AT29211A/US21, AT29286/US21, AT25211A/UA21, AT25286/US21, NT25A21/US21, NT25A31/US21, NT29A41/US21, AT29187/US21, AT29189B/US21, NT25A31, NT25A51/US21, NT25A11/UL21, NT29276/US21, AT25276/US21, AT29128/US21, NT25A11/US21, AT25276G/US21 | RC-R | 13-00AS12-13B | 13-A01V01-PHP | 06-0R0032-B1151 |  |
| 521 | TCL | AT25211A/UL21, AT29128/UL, NT25A21/UL, AT25206/UL, AT2527/UL, AT29128, AT29386/UL, AT34281/UL, AT25211A, AT25289B/UL21, AT29211A, NT25A11, NT25A21, NT34A51/UL, NT25A11UL                                                                                  | RC-R | 13-00AS12-13B | 13-A01V01-PHP | 06-0R1035-D007X |  |
| 522 | TCL | AT25228/S22, AT25288/S22, NT25281C/S22, NT25A61/S22, NT25A81/S22, NT25A41/S22                                                                                                                                                                              | RC-R | 13-00AS12-13B | 13-A01V10-TOP | 06-0N0029-B11D1 |  |
| 523 | TCL | AT29266B/S22, AT29281/S22, AT34266B/S22                                                                                                                                                                                                                    | RC-R | 13-00AS12-13B | 13-A01V10-TOP | 06-0N0029-B11D1 |  |
| 524 | TCL | NT21A51C/S12, NT21A71/S12, NT21A81/S12, NT21A41/S12                                                                                                                                                                                                        | RC-R | 13-00AS12-13B | 13-A01V10-TOP | 06-0N0029-B11D1 |  |