








① 1.5Vp-p H




② 0.9Vp-p H




③ 1.3Vp-p H




④ 3.5Vp-p H




⑤ 3.5Vp-p H




⑥ 3.5Vp-p H




⑦ 1.5Vp-p H




⑧ 6Vp-p H




⑨ 80Vp-p H




⑩ 1100Vp-p H




⑪ 4Vp-p V




⑫ 1.8Vp-p V




⑬ 56Vp-p V




⑭ 5Vp-p H




⑮ 5Vp-p V



⑯ 2.2Vp-p V



⑰ 11Vp-p V

⑱ 580Vp-p
T=30us